

20221072271001

1/6






FIGURE 1




FIGURE 2

202210-12211001

2/6




FIGURE 3




FIGURE 4A




FIGURE 4B




FIGURE 5




FIGURE 6




FIGURE 7




FIGURE 8




FIGURE 9




FIGURE 10A




FIGURE 10B




FIGURE 10C

202210-127488F




FIGURE 11A




FIGURE 11B




FIGURE 12




FIGURE 13A




FIGURE 13B

202210 T22TH001